

03500.017890



Cole
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
SHINYA NODA, et al.) : Examiner: H. Nguyen
Application No.: 10/770,460) : Group Art Unit: 2851
Filed: February 4, 2004) :
For: IMAGE FORMING APPARATUS) :
U.S. Patent No.: 6,909,494) : November 15, 2005
Issued: June 21, 2005) :
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-identified patent:

COLUMN 1

Line 37, "mirror 106a" should read --mirror 106b--.

COLUMN 3

Line 21, "borne, on" shuold read --borne on--.

COLUMN 5

Line 7, "to," should read --to--.

COLUMN 7

Line 14, "there is" should read --is there--

COLUMN 8

Line 1, "mark" should read --mark x--

Line 23, "delivered," should read --being delivered,--; and

Line 36, "delivered" should read --being delivered--.

COLUMN 11

Line 3, "is" should read --are--.

These errors appear to be relatively insignificant and, therefore, we do not believe it is necessary to request a Certificate of Correction. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should be directed to our new address given below.

Respectfully submitted,



Attorney for Patentees
Michael K. O'Neill
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 105019v1